

LAND CORNER RECORD

Index: O-12	Corner: Northeast Sixteenth corner	State of Indiana - Hoosier National Forest		
Section: 21	Township: 7N	Range: 1E	P.M.: 2nd	County: Monroe
Coordinate:	Lat./N: 1378200.03	Lon./E: 3143956.50	Datum: NAD83(2011) US survey feet	


CORNER HISTORY: (Chronological history of corner)

1.) Date of Survey:	Surveyor:	Monument:	Recording Information:	Monument Photograph:
11/23/1982	Ken Anderson USFS	Stone	On file in USFS office	
Reference Objects:	Species:	Diameter:	Bearing:	Distance:
Record evidence of prior survey:	Found limestone			
2.) Date of Survey:	Surveyor:	Monument:	Recording Information:	
06/06/2005	Robert J. Stone USFS	6"x 9" Limestone 9" Above grade	On file in USFS office	
Reference Objects:	Species:	Diameter:	Bearing:	Distance:
	White Oak	27"	S82°W	22.6'
	Red Oak	20"	S66°E	22.0'
	T-post	N/A	North	3.0'
Record evidence of prior survey:	Found limestone			

ACCESSORIES: Bearing and distance from monument to witness object.

Reference Objects:	Object or Tree Species:	Diameter:	Bearing:	Distance:
	Mag nail in White Oak	30"	S81°W	22.41'
	Mag nail in Red Oak	30"	S65°E	22.24'
	Mag nail in Shagbark Hick	10"	N28°E	28.30'
Monument Found or Set:	A 6 inch by 8 inch cut limestone with no markings was found 0.9' above grade.			


MONUMENT SKETCH



NARRATIVE REFERENCE:

Monument is a 6 inch by 8 inch cut limestone with no markings, found 0.9' above grade, a carsonite post is located 1 foot to the west of monument. Located on north facing slope of an east-west running ridge top.

SECTION DIAGRAM



Corner Location = ●

PERPETUATION RECORD:

The origin of this monument is unknown. It is called for in the USA deed recorded in Deed Book 283, Page 500, and is shown on the hand drawn sketch of Section 21 by Ken Anderson, dated 11/23/1982 (on file in the USFS office). It is 3.48 feet north of a line between the stone at O-11 (Center-North Sixteenth) and the pipe at O-13 (North Sixteenth common to Section 21 and Section 22). This position is supported by the 3/4 inch rebar with aluminum cap found marking the property corner at O-12.68, which is on line between this stone and the pipe at O-13. The lines to the north and west have been posted for several years with USFS Property Boundary posts.

The record monument was found undisturbed and maintained by remarking the existing bearing trees or establishing new bearing trees. Two existing bearing trees were recovered from a 6/6/2005 Land Corner Record and remarked. One new bearing tree was established.

Bearing Trees were marked with a blaze, scribed B.T., bearing tree sign, paint, and nail where permission was granted by adjoining landowner.

Section: 21 T7N R1E

Prepared By: BRG (Project#3-565)

Date: 6/2015

Referenced on BRCJ survey recorded as InstNo.2016001724

Accepted by the Monroe County Surveyor Review Board on August 6, 2019.

Index:	O-12	Corner:	NE 1/16	LAND CORNER RECORD				State of Indiana Hoosier National Forest
Twnshp:	7N	Range:	1E	Section:	21	2 nd P.M.	County	Monroe
EXISTING SURVEYS								
Original Government Survey					Original Survey Evidence Found			
Year Surveyed:		By:		Date of Search:		By:		
Original Monument:				Monument Found:				
Species	Diameter	Bearing	Distance	Species	Diameter	Bearing	Distance	
Subsequent Corner Restoration					Evidence of Subsequent Corner Restoration Found			
Where Filed or Recorded:				Year Searched:	6/3/05	By:	B.Stone	
Book:		Page:		Date:				
Monument Set:				Monument Found	6"x 9" squared limestone standing firmly 9" above ground, with a small shallow + on top. The southeast corner is broken off and lying next to it.			
Species	Diameter	Bearing	Distance	Species	Diameter	Bearing	Distance	

OTHER EVIDENCE

Describe corner loc. relative to nearby features & dir. to corner location; note fences, roads, etc. The stone is located at the north edge of a ridgetop. The northwest corner of a Pine stand on the ridgetop is 23 feet south. An old roadbed on the ridgetop is approximately 100 feet west. A treeline runs east and west. The stone was found covered with Greenbriars. Old fence remnants attached to trees and on the ground are running north. The ground to the northeast slopes steeply downhill away from the stone.	Sketch of Monument 
---	--

PERPETUATION RECORD

Monument: Describe new monument set or work done to perpetuate/preserve the existing monument/position.							
							
Corner Diagram			Accessories: Describe new BTs & witness objects established to perpetuate existing evidence.				
			Old bearing trees with healed over blazes, old paint bands and no tags: W.Oak 27" S 82°W 22.6 Ft. R.Oak 20 S 66°E 22.0 Ft. old metal "T" post with metal survey monument sign North 3.0 Ft.				
			Corner Recordation:		Certificate Prepared:		
			Filed and Recorded in County records:		Date:		
			Book:		Page:		
			Section: 21		Geodetic Coordinates:		Lat./N.
		Edited By: Robert J. Stone		Date Created: 6/6/05			

Index No. 012
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7150-4 (Rev. 6/13/67)
GPO 502-127

T. 7N R. 1E 2nd Mer. N.F. Hoozier County Jackson State Ind.
C 1/4 NE 1/4 Corner common to sections 21 and _____

EXISTING SURVEYS

Original Evidence Found

Year of search 1980 By Tim Cummings
Monument found None

Original Bearing Trees Found

Species _____
Diameter _____
Bearing None
Distance _____


Evidence of Subsequent Corner Restoration Found

Year of search 1980 By Tim Cummings

Bearing Trees, Reference Objects

77N R. 1E
C 1/4 NE 1/4 Sec. 21

Found limestone
.5 x 7 x .8
100'± from old trail
on top of ridge, tree
line from S+E. 22.6'
N. easterly from corner
of tree line, fence
corner in 16" W.O. 16" W.O.
N. 87° E. 22.6"



Sketch

○ Corner ▨ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
Object _____
Record distance _____
Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc. Cite source of testimony if any. Limestone w/ 100'± N
of old trail on top of ridge also trail runs by
wild life pond. There is tree lines from S+E
Fence corner 22' to W. of stone, in a 16" W.O.
Fence 30'± N. of stone running E.

Perpetuation Record

Monument and accessories established. Include brief description of area.
B.T. B.T.
W.O. W.O.
16" 6"
N 87° W N 87 1/2° W
22.6' 23'

At time of search:

1. Did you have the record description?
Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. _____

3. Man hours spent in search 5 min.

4. Do you think additional search might
recover evidence? Yes _____ No _____

5. Signature Tim Cummings

Certified corner restoration certificate prepared: Yes _____ No _____
Filed in county records at _____ Date _____ County Document No. _____
Identified on aerial photo No. _____ Which is filed at _____